S.R.C. Project Full List

East Campus

Chapel Dimming Rack Replacement

Worship Arts uses this electrical control cabinet to dim the chapel lighting. The
current light bulbs are more sensitive to voltage changes and have been causing
the lights to flicker. An advancement in our dimming technology is necessary, to
solve these issues and have our lighting work appropriately.

Campus Signage

 To ensure consistency and easier navigation, we are implementing new signs for the East Campus buildings. To align with the standard set by the Welcome Center, we will be implementing clearer and more visible signs with large, black lettering labels.

Renovation of 6 Bathrooms

- 1984 is the last year that six of our bathrooms in the Student Center, Chapel Lobby, and Backstage have been updated. Upgrades to these facilities are due.

Parking Lot Repairs/Resealing

- For safety and convenience, our East Campus parking lot needs some maintenance. This parking lot has yet to be resealed and needs repairs. Not only are there many damaged areas, but the parking lot lines are also very faded.

Grounds Upgrades

 We have not had the opportunity to upgrade the grounds, which are outdated and dying. They require a refresh, to match the interior of our buildings in appearance.

Repair and Paint the Brick Facade - Education Building

In the future, we look forward to repainting the East campus buildings to match the colors of the West Campus. However, for now, we are focused on repairing some areas of the brick facade that have deteriorated and need fresh paint.

Two Parking Lot Poles

- Two of our parking lot poles are rusted and are in need of replacement.

Soffit Repair, Gutter Removal, and Awnings

- The student life and counseling center were originally built without a gutter system. The current added-on gutters are leaking and insufficient. These must be removed and a better water management system implemented. We are also looking to add awnings from building to building to allow for dry access.

Movable Wall Replacement in the Education Building Classrooms

 Our accordion walls in the classrooms are constantly being used for various events, causing them to wear down. These walls are over 30 years old and are in dire need of replacement.

Four-door Replacements for Exterior Doors in the Education Building

 We have four wooden doors that secure the outside of the building that need upgrading. We will replace these doors with aluminum storefronts with glass.

Four Chapel Door Replacements

 For security purposes, the four doors of the chapel need replacing. Due to rust and rot, they are not functioning properly anymore.

Carpet Installation in the Back Hallway of the Chapel and Room 590

- The current flooring in the chapel's hallway and room 590 is 30 years old and we are looking to replace it with carpet.

Courtyard Bollard Replacement

 The current bollard lights are broken and a more modern lighting replacement is needed.

Steeple Removal

 The very top of the steeple is causing major leaks and needs to be taken down to prevent future damage.

West Campus

Carpet Cleaning Machine and Extractor

- There are many large carpeted areas on our campus, yet we do not have a carpet extractor that is sized adequately to clean these spaces.

Hardwood Cleaning Machine

- We are currently using a mop and bucket to clean our hardwood floors. This is both inefficient and out of date. Therefore it was proposed we purchase a hardwood cleaning machine.

Connect Center and Building E Elevator Modernization

- The current elevator in the Connect Center does not have a third door monitoring sensor, which is a requirement in the state of Florida. We are modernizing the elevator's electronics from when it was installed 29 years ago.

Worship Center Dimming Rack and Fixture Replacement

 Worship Arts uses this electrical control cabinet to dim the lighting on the stage during worship. The current light bulbs are more sensitive to voltage changes and have been causing the lights to flicker. An advancement in our dimming technology is necessary, to solve these issues and have our lighting work appropriately.

Connect Center Dimming Rack

- Worship Arts uses this electrical control cabinet to dim the chapel lighting. The current light bulbs are more sensitive to voltage changes and have been causing the lights to flicker. An advancement in our dimming technology is necessary, to solve these issues and have our lighting work appropriately.

Campus Signage - Alphabetical Building Labels and Exterior Door Labels

 Our signs must be updated. This is not only for easier navigation on campus but also for safety reasons. If there is a fire or other emergency someone must be able to clearly explain their location. We can prevent confusion by creating labels for each building for simplicity.

Campus Signage - Wayfinding signage and Site Map of Campus

- For easier navigation, we plan to not only create signs in walkways but also a map for each campus.

SRC Kids' Room 415 Carpet and Kitchen Flooring

 The SRC Kids' building was built in the '90s and this is the last room that is yet to be updated. Room 415 which was being used as a closet, has since been cleared out to make space for more classes.

Parking Lot Exterior Lighting

- The current bulbs we are using in the parking lot are not only out of production but require an immense amount of energy. We are switching to LEDs to provide better lighting, safety, and cost efficiency.

Irrigation Well for West Campus Zones (Giving existing well to field only)

- We need a new well for the entire West campus. We will be taking off city water which is connected to some of our current zones. The current well will still be utilized by the school for its athletics field, and help better maintain their greens.

SRC Kids Sunset and Sunrise Carpet Replacement

 We need to replace the current carpeting in these areas as they are discolored and falling apart.

Lobby Furniture

- We need new, sturdy, and adequate furniture for our lobby. Currently, we are using leftover IKEA furniture from different areas around the church.

Carpeting and Flooring in the Worship Arts Office Hallway and Common Areas

 The carpeting in these areas is outdated and worn. This is an important need, as these spaces are used daily by the staff even more so with the worship band recently recording.

Replacement of Incandescent Fixtures

 The Department of Energy no longer sells or repairs incandescent lights and is projected to ban them entirely in 2025. We must abide by these regulations and switch to LEDs.

Grounds Upgrades

- Our current grounds are still the originals done back in 1998. With lots of it scarce, thinning, and dying away, we need to make some extra improvements in this area.

BAC net and VAV controls for the Connect Center

 To match the other buildings and provide a more monitored temperature system we need to replace our AC controls.

Two Utility Carts

- With the purchase of our East campus, many renovations, and a growing school and campus the facilities team needs more carts to get around.

Controller and Transfer Switch Replacement

 Our transfer switch for the Worship Center sprinkler pump had a broken contactor that switched to the generator. For safety reasons, this contactor must be replaced and a fire company has proposed a way to go about this without replacing the entire cabinet.

Security Window Film

- This security film is necessary for all the Worship Center and children's ministry rooms for extra security against outside threats.

Rigging for Stage Curtains and Lighting

 To pass upcoming inspections, some repairs must be made to the current rigging.

Exterior Door Replacements on the Worship Center's 2nd Floor

 These doors are located within the large mechanical room and are used for roof access. They have endured lots of sun and rain, which has caused them to rot and now require replacing.

Chiller Well

 We require a well for the chiller cooling towers to no longer be charged for drainage/sewage as we do not drain and waste any water within these lines. This well should pay for itself within just one year.

Shuttle Cart Replacement

We need replacement shuttle carts for Sunday service as well as large events.
 This is important for the attendance of those who do not otherwise have transportation.

Worship Arts

Worship Center Dimming Rack and Fixture Replacement:

- The current lighting in the worship center uses bulbs that have become illegal to manufacture in the US. We must upgrade the system to accommodate LED production fixtures that won't flicker when dimmed.

Two Side Projectors

 The two side projectors have been discontinued for over ten years and are no longer supported. Parts are no longer made, and a bulb could go out any Sunday.

Four Profile Fixtures for Front Wash

- As stated above, we are transitioning our outdated lighting products and future-proofing our production environments. These fixtures will be the ones that light the frontline of vocalists.

Front Stage Painting

 To create an immersive environment, we need to start with a blank canvas on the stage's facade. Having it all painted (black) will create a more cohesive look and focus people's attention on the stage; also making lighting elements more impactful.

In-ear Monitor Upgrade

We're currently limited on how many band members we can have on stage.
 This in-ear monitor upgrade will allow us to take the first step towards updating our audio console and, therefore, adding the ability to have more band members on stage.

Drum Kit and Cymbals

- Spanish River Church is writing music! Aside from needing a separate drum kit for studio recording purposes, we have various needs across the campus that justify the need for another drum kit. School chapels, east chapel events, SRC Kids', etc.

Camera Platform

- Getting up and down from our current camera platform has proven to be a safety hazard. We're investing in a more stable and safe camera platform for our operators to avoid falls.

Wireless Intercom - 2 Channels

 Our video team has tripled in size in the last year--praise God! However, we're struggling to fit everyone in regularly. This purchase will allow for two extra camera positions on the stage. These are just the headsets for communication with the video director, but we'll still need to purchase more cameras soon.

PA Tuning and Calibration

- We're in a spot where we know our room needs more acoustic treatment and more PA (speakers) altogether, but we need to find out if we have our system tuned to its optimal settings. This first step towards better audio will give us the best our PA system can provide us and also tell us more accurately what else we need to update soon.